

KHANANSOFT DOCUMENT – SOP

Step 1: Share following details to khanansofthelp@gmail.com

1. Lessee / Stockist/Master ID
2. Owner Name
3. Mobile Number
4. Is this a New Installation? – Yes / No
5. Is this a Reinstallation? – Yes / No
6. District Name
7. Type of Mineral
8. User Type (Lessee/Stockist)

Step 2: Prepare Your System Setup

1. You will need a **computer running Windows 10 or higher**.
2. Connect the computer to the **Web bridge machine** using an **RS-232 connector**.
3. Install the **HyperTerminal driver** on the computer. This will allow you to view the **Weighbridge weight in BIT format**.

Step 3: Web bridge Configuration

1. The **NIC team** will configure your Weigh Bridge.
2. Once setup is complete, you're ready to log into the system.

चरण 1: निम्नलिखित विवरण khanansofthelp@gmail.com पर साझा करें

1. लेसी/ स्टॉकिस्ट /मास्टर ID
2. कंपनी का नाम
3. मालिक का नाम
4. मोबाइल नंबर
5. क्या यह नई इंस्टॉलेशन है? - हां / नहीं
6. क्या यह पुनः इंस्टॉलेशन है? - हां / नहीं
7. जिले का नाम
8. खनिज का प्रकार
9. उपयोगकर्ता प्रकार (लेसी/स्टॉकिस्ट)

चरण 2: अपने सिस्टम सेटअप की तैयारी करें

1. आपके पास **Windows 10** या उच्च संस्करण वाला एक कंप्यूटर होना चाहिए।
2. कंप्यूटर को **RS-232** कनेक्टर का उपयोग करके वेब ब्रिज मशीन से कनेक्ट करें।
3. कंप्यूटर पर **HyperTerminal** ड्राइवर इंस्टॉल करें। इससे आपको वेबब्रिज का वजन **BIT** प्रारूप में देखने में मदद मिलेगी।

चरण 3: वेब ब्रिज कॉन्फ़िगरेशन

1. **NIC** टीम आपके वेब ब्रिज की कॉन्फ़िगरेशन करेगी।
2. कॉन्फ़िगरेशन पूरा होने के बाद, आप सिस्टम में लॉगिन करने के लिए तैयार हैं।